

AVStar Fuel Systems, Inc. 1365 Park Lane South Jupiter, FL 33458

www.avstardirect.com

SERVICE BULLETIN

OVERHAUL PERIODS FOR AVSTAR CARBURETORS

DOCUMENT: AFS-SB7
REVISION: 1
ISSUED: JULY 23, 2014
PAGE: 1 OF 2

1. APPLICABILITY

This Service Bulletin defines the overhaul requirements for carburetors manufactured by AVStar Fuel Systems, Inc.

2. REASON FOR PUBLICATION

To clearly define overhaul requirements to owners of AVStar carburetors.

3. COMPLIANCE

The Time Between Overhaul (TBO) for all carburetors produced by AVStar Fuel Systems, Inc. is the same TBO period as that identified by the manufacturer of the engine for which the carburetor is specified.

Alternatively, overhaul must be performed ten (10) years after the carburetor is placed in service, or ten (10) years after the last overhaul of the carburetor, whichever occurs first.

Under circumstances where the carburetor has been subjected to unusual or untypical environmental conditions, such as, but not limited to, water, fire, particulate contamination or unspecified fuel or liquid, then an immediate overhaul is required.

Overhaul instructions for AVStar carburetors are contained in the appropriate AVStar Overhaul and Repair Manual for the model in question. These are readily available by application through the AVStar website at www.avstardirect,com

4. INSTRUCTIONS FOR COMPLIANCE

FSM LVC-S: Overhaul & Repair Manual, Models - LVC-3-3A/LVC-3-3PA/LVC-5-4PA

FSM LVC-5-5: Overhaul & Repair Manual, Models - LVC-5-5BPA / LVC-5-5PA

Any questions regarding Service Bulletin are to be directed to AVStar Fuel Systems, Inc. at www.avstardirect.com, or call (561) 575-1560



AVStar Fuel Systems, Inc. 1365 Park Lane South Jupiter, FL 33458

www.avstardirect.com

SERVICE BULLETIN

FSM LHC-6-6: Overhaul & Repair Manual, Models - LHC-6-6BA / LHC-6-6BPA

OVERHAUL PERIODS FOR AVSTAR CARBURETORS REVISION: 1 ISSUED: JULY 23, 2014 PAGE: 2 OF 2

DOCUMENT: AFS-SB7